

	<p>Team Bear USA a division of Northwest Equipment Manufacturing, Inc. 122 East Reserve Dr. • Kalispell, MT 59901 USA Office: 866-OWN-BEAR (696-2327) • Fax: 406-755-0813 salesstaff@TeamBearUSA.com</p>	
--	---	--

To Our Customer:

Thank you for purchasing from Team Bear USA, we sincerely appreciate your business and we want you to be happy with your purchase.

If you are used to working with a DOS based Bear CCD alignment system you will notice a few differences in the way the system operates. One of the main differences you will notice is the speed of the runout procedure. It will take longer than the DOS system. This is normal and nothing is wrong with your system. The newer Windows based software has been written to use much tighter parameters for the runout procedure, which results in a higher degree of accuracy. A time of 10 to 20 seconds after the runout button is depressed is normal. A large number of calculations are being performed and your system is waiting for a stable reading from both the vials and cameras.

We are sure you will be pleased with this state of the art wheel alignment system upgrade which will allow your older system to function comparatively to any new wheel alignment system on the market today.